





# YOUR PARTNER IN PLASTIC JOINING

## InfraStake Schematics



### Pneumatic Schematic - No Boss Sensing

InfraStake Pneumatic Diagram with Dual Flow Rate Cooling Air System



### Pneumatic Schematic - With Boss Sensing

InfraStake Pneumatic Diagram with Dual Flow Rate Cooling Air System and Low  
Pressure Boss Sensing



### Electrical Schematic

PM400 Power Supply Electrical Schematic